STRUCTURAL SAFETY AND NATURAL HAZARD PROTECTION OF BUILDINGS (उपविधि संख्या-13.1)

Requirements specified in the following Indian Standards, Codes and guidelines and other documents needs to be observed for structural safety and natural hazard protection of buildings etc:-

a) For General Structural Safety

- 1. IS: 1905 -1987 "Code of Practice for Structural use of unreinforced Masonry (third rivision)" Indian Standards Institution, March 1981
- 2. IS: 1904 -1978 "Code of Practice for Structural Safety of Buildings: Foundations" Indian Standards Institution
- 3. IS: 456 -2000 "Code of Practice for Plain and Reinforced Concrete" Indian Standards Institution, September 2000
- 4. IS: 800 -1984 "Code of Practice for general Construction in Steel" Indian Standards Institution, February, 1985
- 5. IS: 883-1966 "Code of Practice for Design of Structural Timber in Building", Indian Standards Institution, March, 1967
- 6. IS \$75 (Part 2): 1987 "Code of Practice for design loads (other then earthquake) for building and structures: Part 2 Imposed loads (Second revision)
- 7. IS 875 (Part 3): 1988 "Code of Practice for design loads (other then earthquake) for building and structures : Part 3 Wind loads (Second
- 8. IS 875 (Part 5): 1987 "Code of Practice for design loads (other then earthquake) for building and structures: Part 5 Special loads and load combinations (Second revision)

Besides, any other relevant Indian Standards will need to be referred to.

- b) For Earthquake Protection
 - 6. IS: 1893 (Part 1) "Criteria for Earthquake Resistant Design of Structures; General Provisions and Buildings Part 1(fifth Revision)"
 - 7. IS: 13920-1993 "Ductile Detailing of Reinforced Concrete Structures subjected to
 - 8. IS: 4326-1993 "Code of Practice for Earthquake Resistant Design and Construction of Buildings (Second Revision)" October 1993
 - 9. IS: 13828-1993 "Improving Earthquake Resistance of Low Strength Masonary Buildings - Guidelines " August 1993
 - 10. IS: 13827-1993 " Improving Earthquake Resistance of Earthen Buildings -Guidelines "October 1993
 - 11. IS: 13935-1993 "Repair and Seismic Strengthening of Buildings Guidelines" November 1993

For Abha Builders Pvt. Ltd.

उ०प्र० आवार

Director

RAJ KUMAR B.ARCH. COA Regd. No. CA/2006/38039

Dr. Santosh Kumar IES, FIE, Fistr.E, MIRC Ph.D., M. Tech(str), B. Tech (UT-76) M/s Vam Consulting Engineers & Architects (P) Ltd. 7/121 (B), Swaroop Nagar, Kanpur-20800?