

FORM-Q

ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

No.....

Date:30-06-18

**Subject:** Certificate of Percentage of Completion of Construction Work of 13 No. of Building(s)/Block(s) of the 1st Phase of the Project [UPRERAPRJ8547] situated on the Khasra No/ Plot no GH-01A, Sector- 16, Greater Noida Demarcated by its boundaries (28. 36 22 N and 77. 27 33 E of the end points) Plot No.- GH-01B, GH-01C & GH-01F to the North, PLOT NO.- GH-02 to the South, 60.0 MT. Wide Road to the East, 24.0 MT. Wide Road to the West of Greater Noida , Tehsil Gautam Budh Nagar Competent/ Development authority GREATER NOIDA, District GAUTAMBUDH NAGAR, PIN-201306 , admeasuring 41478.04 sq.mts. area being developed by [PANCHSHEEL BUILDTECH PVT. LTD.]

I, Akash Hingorani have undertaken assignment as Architect of certifying Percentage of Completion Work of the 13 Building(s)/Block/ Tower (s) of 1st Phase of the Project, situated on the Khasra No/ Plot no - GH-01A Greater Noida , Tehsil - Gautam Budh Nagar competent/ development authority GREATER NOIDA, District GAUTAMBUDH NAGAR, PIN-201306 admeasuring 41478.04 sq.mts. area being developed by [PANCHSHEEL BUILDTECH PVT. LTD.]

1. Following technical professionals are appointed by owner / Promotor :-

- |       |              |   |                          |
|-------|--------------|---|--------------------------|
| (i)   | M/s/Shri/Smt | AKASH HINGORANI                         | as Architect             |
| (ii)  | M/s/Shri/Smt | OPTIMUM DESIGNS PVT LTD.                | as Structural Consultant |
| (iii) | M/s/Shri/Smt | CONSUMATE ENGINEERING SERVICES PVT LTD. | as MEP Consultant        |
| (iv)  | M/s/Shri/Smt | DEEPAK JAIN                             | as Site Supervisor       |

Based on Site Inspection, with respect to each of the Buildings /Blocks/Towers of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the Buildings /Blocks/Towers of the Real Estate Project as registered vide number UPRERAPRJ8547 under UPRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in the Table B.

Table A (BLOCK-A1)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	2 number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	100%
5	All number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100%



**Table A (BLOCK-A2)**

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	2 number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	100%
5	All number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100%

**Table A (BLOCK-A3)**

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	2 number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	100%
5	All number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100%

**Table A (BLOCK-A4)**

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	2 number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	100%
5	All number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100%



**Table A (BLOCK-A5)**

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	2 number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	100%
5	All number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100%

**Table A (BLOCK-A6)**

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	2 number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	100%
5	All number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100%

**Table A (BLOCK-B1)**

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	2 number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	100%
5	All number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100%



Table A (BLOCK-B2)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	2 number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	100%
5	All number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100%

Table A (BLOCK-B3)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	2 number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	100%
5	All number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100%

Table A (BLOCK-B4)

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	2 number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	100%
5	All number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100%



**Table A (BLOCK-B5)**

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	2 number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	100%
5	All number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100%

**Table A (BLOCK-B6)**

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	2 number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	100%
5	All number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100%

**Table A (BLOCK-B7)**

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	2 number of Basement(s) and Plinth	100%
3	0 number of Podiums	NA
4	Stilt Floor	100%
5	All number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%
9	The external plumbing and external plaster,Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100%



**Table B**  
**Internal & External Development Works in Respect of the Entire Registered Phase**

S No	Common Areas and Facilities, Amenities	Proposed (Yes/No)	Details	Percentage of Work done
1	Internal Roads & Footpaths	yes	ALL WORK IS FINISHED FOR (TOWER A1-A6,B1 TO B7)	100%
2	Water Supply	yes	WATER SUPPLY LINE DONE	100%
3	Sewarage (chamber, lines, Septic Tank, STP)	yes	STRUCTURE WORK HAS COMPLETE	85%
4	Strom Water Drains	yes	STROM WATER DRAINS HAS DONE	100%
5	Landscaping & Tree Planting	yes	LANDSCAPING & TREE PLANTATAION HAS DONE	100%
6	Street Lighting	yes	ALL LIGHTINING WORK HAS DONE	100%
7	Community Buildings	no		
8	Treatment and disposal of sewage and sullage water	yes	STP IS MADE AS PER ENVIORNMENT NORMS	100%
9	Solid Waste management & Disposal	yes	SOLID WASTE DONE THROUGH GARBAGE SHAFT	100%
10	Water conservation, Rain water harvesting	yes	ALL WORK IS FINISHED FOR (TOWER A1-A6,B1 TO B7)	100%
11	Energy management	NA		0
12	Fire protection and fire safety requirements	yes	ALL FIRE PROTECTION WORKS DONE AS PER FIRE NORMS	100%
13	Electrical meter room, sub-station, receiving station	yes	ELECTRICAL METER ROOM,SUB STATION,RECEIVING STATION HAS DONE ON SITE	100%

Yours Faithfully

Signature & Name OF Architect

AKASH M. HINGORANI  
(License NO. COA/92/15430)