ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

No	Date;
Subject:	Certificate of Percentage of Completion of Construction Work of G. K. COMPUEND. of Building(s)/Block(s) of the Phase of the Project [UPRERA Registration Number] situated on the Khasra No/ Plot no332 Demarcated by its boundaries [latitude and longitude of the end points] \(\frac{\omega3'21'54.1'}{24.1'}\) to the North \(\frac{\omega3'21'53.\omega\$to the South \(\frac{26'44'27.1'}{27.1'}\) to the East \(\frac{26'44'27.7'}{26'21'27.7'}\) to the West of village \(\frac{Govakley \omega}{Govakley \omega}\) Tehsil \(\frac{Govakley \omega}{Govakley \omega}\) Sq.mts. area being
	I/We Ashield Srivestan/ Acore Architectural Services I/We Ashield Srivestan/ Acore Architectural Serv
	[Promotor's Name] LOTUS DEVELOPERS 1. Following technical professionals are appointed by owner / Promotor:- (i) M/s/Shri/Smt As Lick Solvestow as L.S. / Architect;
	(iii) M/s/Shri/Smt Rojesh Singh as MEP Consultant (iv) M/s/Shri/Smt Movan Cal as Site Supervisor
	Based on Site Inspection, with respect to each of the Buildings /Blocks/Towers of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the Buildings /Blocks/Towers of the Real Estate Project as registered vide number under UPRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in the Table B.

Table A

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100/2
2	number of Basement(s) and Plinth	100/1
3	number of Podiums	NA
4	Stilt Floor	NA
5	number of Slabs of Super Structure	100%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	78%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	80%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	80%
9	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the Building / Block/Tower	30%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	95%

<u>Table B</u>

Internal & External Development Works in Respect of the Entire Registered Phase

S No	Common Areas and Facilities, Amenities	Proposed (Yes/No)	Details	Percentage of Work done
	Internal Roads & Foothpaths			95%
and the second	2 Water Supply		•	90%
	3 Sewarage (chamber, lines, Septic Tank, STP)			95%
No.	4 Strom Water Drains			95%

	Landscaping & Tree Planting			60%
	Street Lighting			80%
	Community Buildings		Company of the second s	NA
0	Treatment and disposal of			85%
0	sewage and sullage water Solid Waste management & Disposal		The second of th	85%
10	Water conservation, Rain water harvesting			80% 95%
11	Energy management			
	Fire protection and fire safety requirements			98%
	Electrical meter room, sub- station, receiving station	gr. stens.		95%
_	Other (Option to Add more)			

Yours Faithfully
ASHISH SPIVASTAVA
BUARCH, A.I.I.A.
ARCHITECT
C.O.A. Red. No. CA/97/21613
Signature & Name (IN BLOCK LETTERS) OF L.S./Architect
(License NO......)