ARCHITECT'S CERTIFICATE

Subject:	Certificate of Percentage of Completion of Construction Work of Pocket 5 Sector C, SGC No. of Building(s)/ Block(s) of the Mother						
	City Phase of the Project <u>UPRERA PRIJ10125</u> situated on the Khasra No/ Plot no 137, 138, 144, 145, 161, 165, 166, 168, 368, 375 &						
	376.						
	Demarcated by its boundaries 26.783284 to the North, 26.785402 to the South, 81.003114 to the East, 81.004818 to the West of						
	Tobeil Sarolini Nagar Competent/ Development authority Lucknow Development Authority District						
	Lucknow PIN 226002 admeasuring 41000 sq.mts. area being developed by Ansal Properties & Infrastructure Limited.						
	그리고 하고 뭐 하루하게 하셨다. 이번 바까지 않아 먹었다면 하나 되었다면 하는 이번 하는 것이 되었다. 그리고 모든 모든 그						
	I/We have undertaken assignment as Project Engineer for certifying Percentage of Completion Work of the						
	Pocket 5 Sector C, SGC Building(s)/Block/ Tower (s) of Mother City Phase of the Project, situated on the Khasra No/ Plot no 137, 138						
	144, 145, 161, 165, 166, 168, 368, 375 & 376 of village tehsil Sarojini Magar competent/ development authority						
	Lucknow Development Authority District Lucknow PIN 226002 admeasuring 41000 sq.mts. area being developed by Ansal						
	Lucknow Development Authority District Lucknow Pile 22502 dufficial district Lucknow Pile 22502						
	Properties & Infrastructure Limited.						
	This is to certify that I have undertaken assignment of certifying estimated cost and expenses incurred on actual on site						
	This is to certify that I have undertaken assignment of certifying definition of the certificial definit						
	construction for the Real Estate Project mentioned above.						
	1. Following technical professionals were consulted by me for verification /for certification of the cost:						
•	(i) Shri Sanjeev Kumar Singh as Architect						
9.	(ii) Chai Alchiloch laumar Singh as Structural Consultant						
	(iii) M/s/Shri/Smt as MEP Consultant						
	(III) WISSINGOINE						
	(iv) M/s/Shri/Smtas Site Supervisor						
	Based on Site Inspection, with respect to each of the Buildings /Blocks/Towers of the aforesaid Real Estate Project, I certify						
	that as on the date of this certificate, the Percentage of Work done for each of the Buildings /Blocks/Towers of the Real						
h.m. 2007	Estate Project as registered vide numberunder UPRERA is as per table A herein below. The percentage of the						
	work executed with respect to each of the activity of the entire phase is detailed in the Table B.						
	work executed with respect to each of the activity of the offine phase is detailed in the visite as						

Sr. No.	Table A Task/Activity	Percentage Work Done	
1	Excavation	N/A	
2	number of Basement(s) and Plinth	N/A	
3	number of Podiums	N/A	
4	Stilt Floor	N/A	
5	number of Slabs of Super Structure	N/A	
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	N/A	
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	N/A	
. 8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	N/A	
9	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the Building /Block/Tower	N/A	
10	installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	Tanta in the face of the face	

 $\frac{Table\ B}{Internal\ \&\ External\ Development\ Works\ in\ Respect\ of\ the\ Entire\ Registered\ Phase}$

S No	Common Areas and Facilities, Amenities	Proposed (Yes/No)	Details	Percentage of Work	
1	Internal Roads & Foothpaths	Yes	Bitumen Road/CC/Pavers	74	
2	Water Supply	Yes	Deep Bore-well water supplied through Overhead Tank	74	
3	Sewarage (chamber, lines, Septic Tank, STP)	Yes	NP2 Concrete Hume Pipe Network	74	
4	Strom Water Drains	Yes	NP2 Concrete Hume Pipe Network	74	
5	Landscaping & Tree Planting	V	Combination of Indigenous and		
	Candscaping & Tree Flanting	Yes	Ornamental Plants	40	
6	Street Lighting	Yes	Ilumination on Internal Roads	45	
7	Community Buildings	NO	N/A	-	
8	Treatment and disposal of sewage and sullage water	Yes	Connected to STP	. 74	
9	Solid Waste management & Disposal	Yes	House to House Connection	74	
10	Water conservation, Rain water	Yes	Ground Water Recharge System	0	
11	Energy management	Yes	As per Prevailing Laws	1 0	
12	Fire protection and fire safety requirements	Yes	As per NBC Norms	0	
13	Electrical meter room, sub-station, receiving station	Yes	Connected to Township Sub Station, Metered Supply to each & Every Units fromFeeder Pillers	0	
14	Other (Option to Add more)	Yes	Parks, Benches, Pathways	70	

100		and the same of		to the state

Yours Faithfully

Signature & Name (IN BLOCK LETTERS) Or L.S./Architect				
(License	NO)			
	Liaren 🗀	ARCHITECT ON TO		
		SANJEEV KUMAD COM		
	1 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 - 2 -	C.O.A. REG.NoCA/94/17950		