

FORM-Q

ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from **Designated Account)**

No.: BDA/TP NGR/TMIPL/2025/01 Date: 30.01.2025 Subject Certificate of Percentage of Completion of Construction Work of __ SHOPPING COMPLEX TRANSPORT NAGAR BULANDSHAHR 203001__No. of Building(s)/_1_Block(s) of the FIRST Phase of the Project situated on the Khasra No/ Plot no 1 Transport Nagar Scheme Bulandshahr UP Demarcated by its boundaries (latitude and longitude of the end points) 28°24'43.12"N to the South____ 77°49'22.06"E__to the West of TRANSPORT NAGAR SCHEME Tehsil Bulandshahr Competent/ Development authority_BULANDSHAHR DEVELOPMENT AUTHORITY District BULANDSHAHR PIN 203001 admeasuring 2771 sq.mts. area being developed by BULANDSHAHR KHURJA DEVELOPMENT AUTHORITY. We_Tech Mech International Pvt. Ltd.__have undertaken assignment as Architect/Licensed Surveyor of certifying Percentage of Completion Work of the SHOPPING COMPLEX TRANSPORT NAGAR BULANDSHAHR 203001 __Building(s)/_1 __ Block/ Tower (s) of FIRST Phase of the Project, situated on the Khasra No/ Plot no 1 TRANSPORT NAGAR SCHEME of tehsil BULANDSHAHR competent/ development authority_BULANDSHAHR DEVELOPMENT AUTHORITY District BULANDSHAHR PIN 203001 admeasuring 2771 sq.mts. area being developed by BULANDSHAHR KHURJA DEVELOPEMNT AUTHORITY 1. Following technical professionals are appointed by owner / Promotor :-(i) M/s/Shri/Smt HARSHIT SINGHAL as L.S. / Architect M/s/Shri/Smt CHIRAG GARG as Structural (ii) Consultant (iii) M/s/Shri/Smt AJAY KUMAR as MEP Consultant (iv) M/s/Shri/Smt RAHUL RAJPUT(BDA) as Site Supervisor Based on Site Inspection, with respect to each of the Buildings /Blocks/Towers of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for

Designers

Auctioneers

Plannina

Financial Advisory

Engineering

Project Management

of the activity of the entire phase is detailed in the Table B.

Environment Valuations

Legal

Supporting

Certifications/Inspections/Audits



each of the Buildings /Blocks/Towers of the Real Estate Project as registered vide number - under UPRERA is as per table A herein below. The percentage of the work executed with respect to each

Table A

Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	100%
2	0number of Basement(s) and Plinth	50%
3	0number of Podiums	NA
4	Stilt Floor	NA
5	3number of Slabs of Super Structure	50%
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	20%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	50%
9	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the Building /Block/Tower	10%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	10%

	<u>Table B</u> Internal & External Development Works in Respect of the Entire Registered Phase							
S No	Common Areas and Facilities, Amenities	Proposed (Yes/No)	Details	Percentage of Work done				
1	Internal Roads & Foothpaths	YES	the driveway surrounding the building area in the premises is to be made of cement based interlocking tiles.	0%				
2	Water Supply	YES	5000 Liters (2No. Of tanks) on terrace, Each floor water distributed system	5%				
3	Sewarage (chamber, lines, Septic Tank, STP)	YES	Chamber lines are provided and grey water line has been connected to sewer line provided by government	5%				
4	Strom Water Drains	YES	storm water drain has been provided on the terrace and throughout the open area of the site drive way, then the runoff water through collection chambers is pour to rain water harvesting	5%				
5	Landscaping & Tree Planting	YES	centeral open area is provided with landscaping	0%				
6	Street Lighting	YES	on the road facing side	0%				
7	Community Buildings	YES	NA	0%				

8	Treatment and disposal of sewage and sullage water	NO	Chamber lines are provided and grey water line has been connected to sewer line provided by government	0%
9	Solid Waste management & Disposal	NO	dustbins and daily waste collection	0%
10	Water conservation, Rain water harvesting	YES	storm water drain has been provided on the terrace and throughout the open area of the site drive way, then the runoff water through collection chambers is pour to rain water harvesting	0%
11	Energy management	YES	Separate electrical panel room and all electircal equipments contains of ISO rated and less energy consuming electricals ratings	10%
12	Fire protection and fire safety requirements	YES	Electrical Pump Number & Capacity (Litter/Minute) with Pressure 2280 LPM, 56 M. HEAD = 1 NOS., Joockey Pump Number &capacity (Letter/Minute) 180 LPM, 56 M. HEAD = 1 NOS., Diesel Pump Number & Capacity (Letter/Minute) 2280 LPM, 56 M. HEAD = 1 NOS., Sprinkler Diesel Pump Number & Capacity (Litter/Minute): 336, Hoise Reel Lenth (Meter) 30 meters	10%
13	Electrical meter room, sub-station, receiving station	YES	50 KVAR CAPACITOR AUTOMATIC CONTROL PANEL, Incoming Air Circuit Breaker from 250 kVA Transformer - 1, SHOP MAIN METER ELECTRICAL PANEL.(GR., 1ST. & 2ND. FL.), WATER SUPPLY PANEL, FIRE FIGHTING PANEL, ELECTRICAL LIFT PANEL.	10%
14	Other (Option to Add more)	YES	Rolling shutters for the showrooms.	0%

Regards Harshit Singhal General Manager



TECH MECH INTERNATIONAL PVT. LTD. B.Arch. , M.Sc.(elect.), M.Plan. (License NO : CA/2020/125255) Civil Division

+91-8826913664 +91-121-4014700