Space Designers International

ARCHITECTS, PLANNERS, LANDSCAPE & INTERIORS B-34, Sector-67, NOIDA-201301 PH; 91-9711633717, 18, 19, 20

Web: www.spaced.com, Email: info@spaced.com vishal@spacedi.com

FORM-Q

ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

No.:- SDI/JG/09/04

Date: 04.AUG.2018

Subject:

Certificate of Percentage of Completion of Construction Work of <u>JASMINE GROVE</u> of Block 01, Tower-A of the 2 Phase of the Project [UPRERA Registration Number] situated on the Khasra No/ Plot no 959 Demarcated by its boundaries (latitude and longitude of the end points) 28.6697 to the North 28.6697 to the South 77.4863 to the East 77.4863 to the West of village <u>MEHROLI</u> Tehsil <u>GHAZIABAD</u> Competent/ Development authority G.D.A. District <u>GHAZIABAD</u> PIN <u>201002</u> admeasuring <u>5202</u> sq.mts. area being developed by <u>JASMINE GROVE</u>

I/We Space Designer International have undertaken assignment as Architect/Licensed Surveyor of certifying Percentage of Completion Work of the <u>JASMINE GROVE</u> of Block 01, Tower -<u>A</u> of the 02 Phase of the Project, situated on the Khasra No/ Plot no <u>959</u> of village <u>MEHROL</u>I tehsil <u>GHAZIABAD</u> competent/ development authority G.D.A. District <u>GHAZIABAD</u> IN 201002 admeasuring 5202 sq.mts. area being developed by <u>JASMINE GROVE</u>

- 1. Following technical professionals are appointed by owner / Promotor :-
- (i) M/s/Shri/Smt SPACE DESIGNERS INTERNATIONAL as L.S. / Architect;
- (ii) M/s/Shri/Smt OPTIMUM DESIGN (P.) LIMITED as Structural Consultant
- (iii) M/s/Shri/Smt CONSUMMATE ENGINEERING SERVICES (P) LTD as MEP Consultant
- (iv) M/s/Shri/Smt Kausar husain as Site Supervisor

Based on Site Inspection, with respect to each of the Buildings /Blocks/Towers of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the Buildings /Blocks/Towers of the Real Estate Project as registered vide number UPRERAPRJ6920 under UPRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in the Table B.

Table A


| | | Percentage Work Done |
|---------|--|----------------------|
| Sr. No. | Task/Activity | 100% |
| 1 | Excavation | 100% |
| 2 | 02 number of Basement(s) and Plinth | N/A |
| 3 | 0 number of Podiums | |
| 4 | Stilt Floor | N/A |
| 5 | 19 number of Slabs of Super Structure | 100% |
| 6 | Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises | 100% |
| 7 | Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises | 100% |
| 8 | Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks | 100% |
| 9 | The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the Building /Block/Tower | 100% |
| 10 | Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate | 100% |

<u>Table B</u>
Internal & External Development Works in Respect of the Entire Registered Phase

| S No | Common Areas and Facilities, Amenities | Proposed (Yes/No) | Details | Percentage of Work done |
|------|---|----------------------|---------|-------------------------|
|------|---|----------------------|---------|-------------------------|

| 1 | Internal Roads & Foothpaths | yes | IN FORNT OF TOWER-A AND TOWER-B | 100% |
|-----|---|-----|---------------------------------|------|
| 2 | Water Supply | yes | | 80% |
| | Sewarage (chamber, lines, Septic Tank, STP) | yes | | 95% |
| 4 | Strom Water Drains | yes | | 80% |
| 5 | Landscaping & Tree Planting | yes | IN FORNT OF TOWER-A AND TOWER-B | 100% |
| 6 | Street Lighting | yes | IN FORNT OF TOWER-A AND TOWER-B | 100% |
| 7 | Community Buildings | yes | | 50% |
| 8 | Treatment and disposal of sewage and sullage water | yes | • | 35% |
| 9 | Solid Waste management & Disposal | yes | | 50% |
| 10 | Water conservation, Rain water harvesting | yes | | 100% |
| 11 | Energy management | yes | | 30% |
| 12 | Fire protection and fire | yes | | 100% |
| 13 | Electrical meter room, sub- station, receiving station | yes | | 100% |
| 1.4 | Other (Option to Add more) | | | |

Yours Faithfully



Signature & Name of Architect: AR. VISHAL MITTAL (License NO CA/98/23185)

Space Designers International

ARCHITECTS, PLANNERS, LANDSCAPE & INTERIORS

B-34, Sector-67, NOIDA-201301 PH; 91-9711633717, 18, 19, 20

Web: any spaced con, Email: inlogispased.com vishal@spaced.com

FORM-Q

ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

No.:- SDI/JG/09/05 Date: 04.AUG.2018

Subject:

Certificate of Percentage of Completion of Construction Work of JASMINE GROVE of Block 01, TOWER - B of the 2 Phase of the Project [UPRERA Registration Number] situated on the Khasra No/ Plot no 959 Demarcated by its boundaries (latitude and longitude of the end points) 28.6697 to the North 28.6697 to the South 77.4863 to the East 77.4863 to the West of village MEHROLI Tehsil GHAZIABAD Competent/ Development authority G.D.A. District GHAZIABAD PIN 201002 admeasuring 5202 sq.mts. area being developed by JASMINE GROVE

I/We Space Designer International have undertaken assignment as Architect/Licensed Surveyor of certifying Percentage of Completion Work of the <u>JASMINE GROVE</u> of Block 01,Tower - <u>B</u> of the 2 Phase of the Project, situated on the Khasra No/ Plot no <u>959</u> of village <u>MEHROL</u>I tehsil <u>GHAZIABAD</u> competent/ development authority G.D.A. District <u>GHAZIABAD</u> IN 201002 admeasuring 5202 sq.mts. area being developed by <u>JASMINE GROVE</u>

- 1. Following technical professionals are appointed by owner / Promotor :-
- (i) M/s/Shri/Smt SPACE DESIGNERS INTERNATIONAL as L.S. / Architect;
- (ii) M/s/Shri/Smt OPTIMUM DESIGN (P.) LIMITED as Structural Consultant
- (iii) M/s/Shri/Smt CONSUMMATE ENGINEERING SERVICES (P) LTD as MEP Consultant
- (iv) M/s/Shri/Smt Kausar husain as Site Supervisor

Based on Site Inspection, with respect to each of the Buildings /Blocks/Towers of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the Buildings /Blocks/Towers of the Real Estate Project as registered vide number <u>UPRERAPR.J6920</u> under UPRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in the Table B.

| Sr. No. | Task/Activity | Percentage Work Done |
|---------|--|----------------------|
| 1 | Excavation | 100% |
| 2 | 02 number of Basement(s) and Plinth | 100% |
| 3 | 0 number of Podiums | N/A |
| 4 | Stilt Floor | N/A |
| 5 | 19number of Slabs of Super Structure | 100% |
| 6 | Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises | 90% |
| 7 | Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises | 50% |
| 8 | Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks | 80% |
| 9 | The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the Building /Block/Tower | 90% |
| 10 | Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate | 60% |

Table B Internal & External Development Works in Respect of the Entire Registered Phase

| S No | Common Areas and Facilities, Amenities | | Details | Percentage of Work done |
|------|---|--|---------|-------------------------|
|------|---|--|---------|-------------------------|

| 1 Internal Roads & Foothpaths | yes | IN FORNT OF TOWER-A AND TOWER-B | 100% |
|---|-----|---------------------------------|------|
| 2 Water Supply | yes | | 80% |
| 3 Sewarage (chamber, lines, Septic Tank, STP) | yes | | 95% |
| 4 Strom Water Drains | yes | | 80% |
| 5 Landscaping & Tree Planting | yes | IN FORNT OF TOWER-A AND TOWER-B | 75% |
| 6 Street Lighting | yes | IN FORNT OF TOWER-A AND TOWER-B | 55% |
| 7 Community Buildings | yes | | 40% |
| 8 Treatment and disposal of sewage and sullage water | yes | | 35% |
| 9 Solid Waste management & Disposal | yes | | 50% |
| Water conservation, Rain water harvesting | yes | | 100% |
| 11 Energy management | yes | | 30% |
| Fire protection and fire safety requirements | yes | | 100% |
| Electrical meter room, sub- station, receiving station | yes | | 75% |
| 14 Other (Option to Add more) | | | |

Yours Faithfully



Signature & Name of Architect: AK, VISHAL MITTAL (License NO CA/98/23185)

Space Designers International

ARCHITECTS, PLANNERS, LANDSCAPE & INTERIORS

B-34, Sector-67, NOIDA-201301

Web: www.spacedi.com, Email: info@spacedi.com vishal@spacedi.co PH; 91-9711633717, 18, 19, 20

FORM-Q

ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Moncy from Designated Account)

No.:- SDI/JG/09/06

Date: 04.AUG.2018

Subject: Certificate of Percentage of Completion of Construction Work of JASMINE GROVE of Block 02, Tower -C of the 2 Phase of the GHAZIABAD Competent/ Development authority G.D.A. District GHAZIABAD PIN 201002 admeasuring 5202 sq.mts. area being of the end points) 28.6697 to the North 28.6697 to the South 77.4863 to the East 77.4863 to the West of village MEHROU Tehsil Project [UPRERA Registration Number] situated on the Khasra No/ Plot no 959 Demarcated by its boundaries (latitude and longitude developed by JASMINE GROVE

Work of the JASMINE GROVE of Block 02, Tower - C of the 2 Phase of the Project, situated on the Khasra No/ Plot no 959 of village I/We Space Designer International have undertaken assignment as Architect/Licensed Surveyor of certifying Percentage of Completion being developed by JASMINE GROVE MEHROLI tehsil GHAZIABAD competent/ development authority G.D.A. District GHAZIABAD IN 201002 admeasuring 5202 sq.mts. area

- Following technical professionals are appointed by owner / Promotor :-
- M/s/Shri/Smt SPACE DESIGNERS INTERNATIONAL as L.S. / Architect;
- (ii) Θ M/s/Shri/Smt OPTIMUM DESIGN (P.) LIMITED as Structural Consultant
- 3 M/s/Shri/Smt CONSUMMATE ENGINEERING SERVICES (P) LTD as MEP Consultant
- M/s/Shri/Smt Kausar husain as Site Supervisor

number UPRERAPR.16920 under UPRERA is as per table A herein below. The percentage of the work executed with respect to each of Based on Site Inspection, with respect to each of the Buildings /Blocks/Towers of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the Buildings /Blocks/Towers of the Real Estate Project as registered vide the activity of the entire phase is detailed in the Table B.

| | lable A | |
|-----------|--|----------------------|
| No. | St. No. Task/Activity | Percentage Work Done |
| 54 | Exceletion | 100% |
| ы | 02 number of Sesement(s) and Plinth | 100% |
| w | O number of Podiums | AIN |
| | Stit Floor | N/A |
| UI | 19 number of Stabs of Super Structure | 30% |
| n | Internal walls, internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises | , |
| | | 10% |
| 7 | Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises | %0 |
| 69 | Staircases, Ufit Wells and Lobbies at each Floor level connecting Staircases and Ufits, Overhead and | |
| | Underground Water Tanks | 0% |
| w | The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the Building Speck Tower | %0 |
| | Installation of lifes, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing | |
| В | to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate | |
| | | 0% |

Internal & External Development Works in Respect of the Entire Registered Phase

| Common Areas a Facilities, Amenia |
|--------------------------------------|
| ad Proposed its (YesNo) |
| Details |
| Percentage of Work done |

SYS

| I Internal Roads & Foothpaths | yes | IN FORNT OF TOWER-A AND TOWER-B | 50% |
|--|-------|---------------------------------|------|
| 2 Water Supply | yes | | 80% |
| Sewarage (chamber, lines, Septic Tank, STP) | yes | | 95% |
| 4 Strom Water Drains | yes | | 80% |
| 5 Landscaping & Tree Planting | yes . | IN FORNT OF TOWER-A AND TOWER-B | 75% |
| 6 Street Lighting | yes | IN FORNT OF TOWER-A AND TOWER-B | 55% |
| 7 Community Buildings | yes | | 40% |
| 8 Treatment and disposal of sewage and sullage water | yes | | 35% |
| 9 Solid Waste management & Disposal | yes | | 50% |
| Water conservation, Rain water harvesting | yes | | 100% |
| 11 Energy management | yes | | 30% |
| Fire protection and fire safety requirements | yes | | 100% |
| Electrical meter room, substation, receiving station | yes | | 100% |
| 14 Other (Option to Add more) | | | |

Yours Faithfully



Signature & Name of Architect: AR. VISHAL MITTAL (License NO CA/98/23185)