No.....

ARCHITECTS, ENGINEERS, PLANNER VALUER, INTERIOR DESIGNERS

VIBHUTI KHAND, GOMTI NAGAR LUCKNOW-226 010, PHONE: 0522-4065958

108, FIRST FLOOR CORPORATE CHAMBER-1 e-mail: espaces_arch@rediffmail.com

Subject: Certificate of Percentage of Completion of Construction Work of SOUTH BLOCK, Eldeco Shaurya sq.mts. area being developed by [Promotor's Name]- Eldeco Housing & Industries Ltd. to the East. 80° 53' 24.1" E to the West of village Latur, Bijnore road, LIDA Tehsil Lucknow situated on the Khasra No/ Plot no. 627 & 848 & Others Demarcated by its boundaries (latitude and Competent/ Development authority LIDA District LUCKNOW PIN No. of Plots/Building(s)/ 13 No. of the Project [UPRERA Registration Number- UPRERAPRJ18732 longitude of the end points) 26° 43' 10.8" N to the North 80° 53' 24.1" E to the South 26° 43' 10.8" N admeasuring 2921.2

being developed by [Promotor's Name]- Eldeco Housing & Industries Ltd. development authority LIDA District LUCKNOW PIN Completion Work of the South Block, Shaurya Plots/Building(s) of the Project, situated on the Khasra No/ I/We ESPACES have undertaken assignment as Architect/Licensed Surveyor of certifying Percentage of admeasuring 2921.22sq.mts. area

Following technical professionals are appointed by owner / Promotor :-

- M/s/Shri/Smt SANJAY KUMAR GUPTA as L.S. / Architect;
- M/s/Shri/Smt ATS Structural Consultants as Structural Consultant

 Ξ Ξ

- M/s/Shri/Smt H&C Consultants as MEP Consultant
- M/s/Shri/Smt Ajay as Site Supervisor

as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in the Table B. Blocks/Towers of the Real Estate Project as registered vide number UPRERAPRJ18732 under UPRERA is Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the Buildings Based on Site Inspection, with respect to each of the Buildings /Blocks/Towers of the aforesaid Real Estate

FORM-Q

Date: 02/02/2019

ARCHITECT'S CERTIFICATE

Table A

	I ADIC A	
Sr. No.	Task/Activity	Percentage Work Done
1	Excavation	0.00%
2	number of Basement(s) and Plinth	N.A.
3	number of Podiums	N.A.
4	Stilt Floor	N.A.
5	Slabs of Super Structure	
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	0.00%
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	0.00%
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	0.00%
9	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the Building /Block/Tower	0.00%
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain	N.A.

Table B

Internal & External Development Works in Respect of the Entire Registered Phase

2/4/9

		,							111			_
14	13	12	11	10	9	8	7	6	5	4	3	2
14 Other (Option to Add more)	Electrical meter room, substation, receiving station	Fire protection and fire safety requirements	Energy management	Water conservation, Rain water harvesting	9 Solid Waste management & Disposal	8 Treatment and disposal of sewage and sullage water	Community Buildings	6 Street Lighting	Landscaping & Tree Planting	4 Strom Water Drains	Sewarage (chamber, lines, Septic Tank, STP)	2 Water Supply
							*					
NA	0.00%	0.00%	0.00%	0.00%	0.00%	0.00%	NA	0.00%	0.00%	0.00%	0.00%	0.00%

Yours Faithfully

AF. SANJAY KUMAR GUPTA*

Signature & Name OF L.S./Architect (License NO- CA/89/12382)

Dated- 02/02/2019