ARCHITECT'S CERTIFICATE

(To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)

Subject:

Date: 31.07.2018

Certificate of Percentage of Completion of Construction Work of Golf view apartments, 3 No. of Building(s)/ A Block(s) of the 1st Phase of the Project [UPRERA Registration Number] situated on the Khasra No/ Plot no 21,22,33,35,45,65 Demacated by its boundaries (latitude and longitude of the end points) 26°46′15.94" to the North 26°46′10.72" to the South 80°59′58.33" to the East Bodinicalies (latitude and rongitude of the end points) to 49 23.57 for the West of village Devanda, Sector -1, Pocket D, Sushant golf city, Lucknow Tehsil N/A Competenty Development authority Lucknow District Lucknow PIN 226030 admeasuring 13891 sq.mts. area being developed by Tulsiani Construction & Developers Ltd.

I/We Ms. Ruchi Mishra have undertaken assignment as Architect/Licensed Surveyor of certifying Percentage of Completion Work of the Golf view apartments, 3 No. of Building(s)/ A Block/Tower (s) of 1st Phase of the Project, situated on the Khasra No/ Plot no 21,22,33,35,45,65 of village Devamau, Sector – I, Pocket D, Sushant Hi Tech city, Lucknow tehsil N/A competent/ development authority Lucknow District Lucknow PIN 226030 admeasuring 13891 sq.mts. area being developed by Tulsiani Construction & Developers Ltd.

- 1. Following technical professionals are appointed by owner / Promotor :-
- (i) (ii)
- M/s/Shri/Smt Ms. Ruchi Mishra as L.S. / Architect; M/s/Shri/Smt D & R Consultants as Structural Consultant
- M/s/Shri/Smt Sunil Nayvar Consultant Pvt. Ltd. as MEP Consultant
- M/s/Shri/Smt as Site Supervisor

Based on Site Inspection, with respect to each of the Buildings /Blocks/Towers of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the Buildings/Blocks/Towers of the Real Estate Project, a registered vide number 16247 under UPRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in the Table B.

Table A

Sr. No.	Task/Activity	Percentage Work Done 100%	
1	Excavation		
2	0 number of Basement(s) and Plinth	100%	
3	0 number of Podiums	•	
4	Stilt Floor	100%	
5	58number of Slabs of Super Structure	100%	
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	100%	
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	100%	
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	100%	
9	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the Building /Block/Tower	100%	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	100%	

Table B Internal & External Development Works in Respect of the Entire Registered Phase

No	Common Areas and Facilities, Amenities	Proposed (Yes/No)	Details	Percentage of Work done
1	Internal Roads & Foothpaths		Internal Road Completed and Foothpaths not proposed.	100%
2	Water Supply		Block-A all area water supply completed	100%
3	Sewarage (chamber, lines, Septic Tank, STP)		Block-A all area of Sewarage (chamber, lines, Septic Tank, STP) Completed	100%
4	Strom Water Drains		Completed	100%
5	Landscaping & Tree Planting		Completed	100%
6	Street Lighting		Completed	100%
7	Community Buildings		Completed	100%
8	Treatment and disposal of sewage and sullage water		Completed	100%
9	Solid Waste management & Disposal		Completed	100%
10	Water conservation, Rain water harvesting		Completed	100%
11	Energy management	NO	NA	
12	Fire protection and fire safety requirements		Completed	100%
13	Electrical meter room, sub- station, receiving station		Completed	100%
14	Other (Option to Add more)		Completed	95%

RUCHI MISHRA Yours Faithfully Signature & Name (IN BLOCK LETTERS) OF L.S./Architect Reg. No. CA/2008/43324

(License NO.....