4	Strom Water Drains	Yes	In Ingress.		
5	Landscaping & Tree Planting	Yes			
6	Street Lighting	Yes			ì
7	Community Buildings	No			
. 8	Treatment and disposal of sewage and sullage water	Yes	bonnested to External bonset line.		
9	Solid Waste management & Disposal	res	150		
10	Water conservation, Rain water harvesting	75	Rain water travecting.		-
11	Energy management	પ હ			1
. 12	Fire protection and fire safety requirements	Yez	,		
13	Electrical meter room, sub- station, receiving station	Yes			1
14	4 Other (Option to Add more)	-		, , , , , , , , , , , , , , , , , , ,	1

Yours Faithfully

(NAMIT AGARWAL) ARCHITECT COANO. CA/2006/37491

Signature & Name (IN BLOCK LETTERS) OF L.S./Architect (License NO.....)

FORM-Q

ARCHITECT'S CERTIFICATE

((To be submitted at the time of Registration of Ongoing Project and for withdrawal of Money from Designated Account)
No	UPRERAPRJ 13717 Date:
Subject:	Certificate of Percentage of Completion of Construction Work of Magha Apartment No. of Building(s)/ 1 Block(s) of the Phase of the Project [UPRERA Registration Number] situated on the Khasra No/ Plot no C-1 Section-0. Managerous Scheme Demarcated by its boundaries (latitude and longitude of the end points) 26 46 3231 to the North 26 46 2920 to the South 80 54 05-17 to the East 80 54 03-79 to the West of village know Tehsil [Know Competent/ Development authority Licknow District PIN 226002_ admeasuring 3952-00 sq.mts. area being developed by [Promotor's Name]
N	I/Wehave undertaken assignment as Architect/Licensed Surveyor of certifying Percentage of Completion Work of the Moaha Aportment Building(s)/Block/ Tower (s) ofPhase of the Project, situated on the Khasra No/ Plot no C-1, Sector-0, Manuarous Schemeof village Lucknow tehsilcompetent/ development authorityDistrict Lucknow PIN admeasuring 3952.00 sq.mts. area being developed by [Promotor's Name]
	1. Following technical professionals are appointed by owner / Promotor: (i) M/s/Shri/Smt /// Muralage as L.S. / Architect; (ii) M/s/Shri/Smt // Mis Muralage as Structural Consultant (iii) M/s/Shri/Smt // as MEP Consultant (iv) M/s/Shri/Smt as Site Supervisor
	But a Site Investigation with respect to each of the Buildings /Blocks/Towers of the aforesaid Real Estate Project, I certify that as on

Based on Site Inspection, with respect to each of the Buildings /Blocks/Towers of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the Buildings /Blocks/Towers of the Real Estate Project as registered vide number 15 13717 under UPRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in the Table B.

Sr. No.	Table A Task/Activity	Percentage Work Done
1	Excavation	100%
2		100 V.
3		100 %
4	Stilt Floor	
5	5+6 number of Slabs of Super Structure	100 1
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	60 %
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	٥٧.
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	10 7,
9	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the Building /Block/Tower	50 Y,
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	ογ.

Internal & External Development Works in Respect of the Entire Registered	Phase

S No Facilities, Amenities	Proposed (Yes/No)		Percentage of Work
1 Internal Roads & Foothpaths	Yes	In Progress	ready continued to
2 Water Supply	Yes	In Propers	
Sewarage (chamber, lines, Septic Tank, STP)	102	In Progress	ereses er