

## ARCHITECT'S CERTIFICATE

FORM-Q

I/We Amit Agarwal have undertaken assignment as Architect/Licensed Surveyor of certifying Percentage of Completion Work of the 364 Building(s)/ 3 Block/Tower (s) of 1st Phase of the Project, situated on the Khasra No/ Plot no 126/127 of village Satoha tehsil Mathura competent/ development authority MVDA District Mathura PIN 281004 admeasuring 18463 sq.mts. area being developed by SJP RESIDENCY CONSORTIUM LTD.

- 1. Following technical professionals are appointed by owner / Promotor :-
- (i) M/s/Shri/Smt Virender Associates as L.S. / Architect;
- (ii) M/s/Shri/Smt Sanrachna Consultants as Structural Consultant
- (iii) M/s/Shri/Smt Virender Associates as MEP Consultant
- (iv) M/s/Shri/Smt D S Chauhan as Site Supervisor

Based on Site Inspection, with respect to each of the Buildings /Blocks/Towers of the aforesaid Real Estate Project, I certify that as on the date of this certificate, the Percentage of Work done for each of the Buildings /Blocks/Towers of the Real Estate Project as registered vide number RERAPRJ7603 under UPRERA is as per table A herein below. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in the Table B.

Table A

Sr. No.	Task/Activity	Percentage Work Done	
1	Excavation	100%	
2	number of Basement(s) and Plinth	N A	
3	number of Podiums	N A	
4	Stilt Floor	N A	
5	number of Slabs of Super Structure	80%	
6	Internal walls, Internal Plaster, Flooring within Flats/Premises, Doors and Windows in each of the Flats/Premises	75%	
7	Sanitary Fittings within the Flat/Premises, Electrical Fittings within the Flat/premises	60%	
8	Staircases, Lift Wells and Lobbies at each Floor level connecting Staircases and Lifts, Overhead and Underground Water Tanks	80%	
9	The external plumbing and external plaster, Elevation, completion of terraces with waterproofing of the Building /Block/Tower	70%	
10	Installation of lifts, water pumps, Fire Fighting Fittings and Equipments as per CFO NOC, Electrical fittings to Common Areas, electro-mechanical equipments, Compliance to conditions of environment/CRZ NOC, Finishing to entrance lobby/s, plinth protection, paving of areas appurtenant to Building /Block/Tower, Compound Wall and all other requirements as may be required to obtain Occupation/Completion Certificate	50%	

 $\frac{Table\ B}{Internal\ \&\ External\ Development\ Works\ in\ Respect\ of\ the\ Entire\ Registered\ Phase}$ 

S No	Common Areas and Facilities, Amenities	Proposed (Yes/No)		Percentage of Work done
	Internal Roads & Foothpaths	Yes .	WBM Complete , Part PAVER Road Complete	75%
	2 Water Supply	Yes	Supply Lines laid	80%
	3 Sewarage (chamber, lines, Septic Tank, STP)	Yes	Sewerage lines & Main Hole	80%
	4 Strom Water Drains	Yes	Pipe Line & Main Hole	80%
	5 Landscaping & Tree Planting		Complete	100%
	6 Street Lighting		Partially Complete	60%
	7 Community Buildings		Yet to be started	0%
	8 Treatment and disposal of sewage and sullage water		STP Installed	100%
J	9 Solid Waste management & Disposal		N A	N A
I	Water conservation, Rain water harvesting	1	R W H to be constructed	33%
1	1 Energy management	171	N A	N A
1	2 Fire protection and fire safety requirements		N A	N A
1	3 Electrical meter room, sub- station, receiving station		Partially done	30%
14	4 Other (Option to Add more)			

Yours Faithfully M/s Amit Agarwal

Architect Amit Agrawal (License NO .....)